

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
DSI 9774-011	DSI 9774 REV. A	Y	Y	Y	N	Y	Y	Y	17-555	ADDITION OF HARDWARE AND RELATED INSTRUCTIONS PER AWPC/LHD.

Description of Issue:
 AGUSTAWESTLAND PHILADELPHIA / LEONARDO HELICOPTERS DIVISION REQUESTED A CHANGE TO DSI 9774 DUE TO A TC CHANGE.
 DSI 9774-011 TO INCLUDE HARDWARE REQUIRED TO FASTEN THE ELECTRICAL BONDING CABLES TO THE AFT CROSSTUBE CLAMPS.
 THIS CHANGE IS DRIVEN BY CUSTOMER SUPPORT CASE 9671.

Distribution:	VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
----------------------	--	---	--	--------------------------------------